

# Manhole Inspection Summary

Manhole # S11E\_\_007MH

Printed On: 6/24/2010

Page 1 of 3

## Inspection

☐ Is Incomplete Rating:

Record Plat: **11E** Node: **007** Status: **Abandoned**

Insp Date: **9/28/09 2:54 PM**

Incomplete Comments

**ABD**

Crew: **TJ**  
Inspector: **Johnson**  
Firm: **URS**

## Location

Address: **ELLCOTT DWY**

Cross Street: **EDMONDSON AVE**

## Manhole

Type:

Location:

Ground Conditions:

☐ Prev. Rehab

Weather: **Dry**

Subject To Ponding: **None**

Comments **ABANDONED**

## Cover

Shape:

Diameter: (in.) Length: (in.) Dist A/B Grade: (in.)

Type: **Sanitary**

Condition:

Cover Material: **Cast Iron**

Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

## Frame

Offset: (in.) Condition: ☐ Sound ☐ Cracked ☐ Leaks

## Chimney / Frame Adjustment

☐ Exists Material: ☐ Parged Height: (in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

## Corbel

Material: ☐ Parged Type:

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

## Barrel

Material: ☐ Parged

Shape: Diameter: (in.) Length: (in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

## Bench

☐ Exists Material: ☐ Parged

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

## Channel

Material: ☐ Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

## Steps

Count: Missing: ☐ Corroded

## Surcharge

☐ Evidence Of Surcharge Depth: (ft.) ☐ Active Surcharge Present



